
CITY OF BALTIMORE WET SMOKE AND DYED	Page 1 of 3			
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/03/2008		
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04		
Manhole ID: S19I044MH	Test ID: 1029-595	Notifications Made:X_ Residents, Fire, 311		

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM							Page 2 of 3					
;	Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO					co	Date: 09/03/2008				
	Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_						Supervisor: E.R. Crew: 04				
Ma	anhole ID: S19I044MH		Test ID: 1029-595					Notifications Made:X Residents, Fire, 311				
Field SI	ketch: (Show all manholes with nun		blower pla							ons, s	treet names, building addresse	S
Defect No.		110 100	Source Type			Sector	Drai	nage ea			Photo Number	
1	S19I 021MH		10	1.	4	01		25	03		1029-595_OB01-01.jpg	_
												_
												_
												_
												_
												_
												_
												_
												_
												_
												_
												_
												_
												_
							-					_
												_
			OR	SED.	\/	ION CO	DES					
	Source Type	1	OB	Loca		1014 00	DLO		Sector	1	Severity	
01 Ms	ain Sewer 10 MH Frame	01	Paved C			Non-Pa	ved		Public	01	No Smoke	
02 Service Line 11 Storm Drain 02 Asphal					Field/W			Private	_	Trace	_	
	eanout 12 Catch Basin		Paved C	Other							Moderate	_
	ownspout 13 Storm MH		Drivewa			Golf Co	urse				Major	_
	ea Drain 14 Storm Ditch		Sidewal			Other					,	_
	vy. Drain 15 Excavation		Curb									_
	air. Drain 16 Water Line		Yard - F	ront								_
	ound. Drai 17 Tele. Pole		Yard - B									_
	dg. Interio 18 Other		Yard - S									

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 595 Date: 09/03/2008 Basin: LL - 44 Manhole ID: S19I__044MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: S19I__021MH

Source Type: 10 Other Sector: 01 Public

Location: 14 Other Severity: 03 Moderate Drainage Area: 25 Comments: CANNOT LOCATE MANHOLE \$191_021MH BUT HEAVY \$MOKE IS COMING FROM THE

APPROXIMATE AREA.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-595_OB01-01.jpg